

INSPECTION REPORT

To:	XXXXX			Attn:	XXX					
From:	XXXXX			Report Date:	19-May-2016					
Vendor Name		XXXXX								
Factory Name			C Fluid Control CO., I	td						
Factory Address	· · · · · · · · · · · · · · · · · · ·		ejiang, China							
Order No. / PO No.		S200918662								
Product description:			LE BRASS BIBCOCK WITH	ADAPTOR1/2" X 3/4" CP						
•		ABS HANDLE I	BRASS ANGLE VALVE WIT							
Inspection Date:		: 19-May-201	0							
Inspection Method A	oplied: (A	NSI / ASQ Z1.4	- 2008)							
Single Sampling Plan	s for Norma	al Inspection:	□S-4/ □L-1/ ⊠L-	II / 🗌 Special:						
			Critical:	N/A	Y					
Acceptance Quality	Level (AQL	_) for:	Major	<u>1.5</u>						
			Minor	<u>4.0</u>						
Inspection Criteria :										
Purchase Order		ence sample	Product Specificatio	ns 🗌 Artwork	\boxtimes Other documents \square N/A					
Overall Result:				RTIVE						
INSPECTION RESU	JLT									
Part 1 – PO Quanti	ty & Availa	bility	Conformed	Not Conforme	d 🗌 Pending					
Part 2 - Appearanc Workmanship	e, Functio	ning and	Conformed	Not Conforme	d Pending					
Part 3 - Field tests			Conformed	Not Conforme	d 🗌 Pending					
Part 4 - Packaging Conformity	and Produ	ict	Conformed	Not Conforme	d Pending					
Part 5 - Data meas	arement		Conformed	Not Conforme	d 🗌 Pending					
		¢	L		1					
Special Attention:										
					card conform to TCF and PO					
Informative remark		but not conform to ref.sample. Confirmed by client								
			For item 934778 and 934780, found: "porto de destino: Santos, Brasil " not conform PO: "ENTREPOT SERTRADING SAO PAULO". Confirmed by client.							
		UFU. ENTR	LF OT SERTRADING	SAU FAULU . CUIIII						

V1.0 Page 1 of 15

TIS Troika Inspection Service Your Quality Solution Partner

Report No.:TIS-CTS-00000

1. PO Quantity & Availability:

\boxtimes Conformed \square Not Conformed \square Pending

Article	PO No.	ΡΟ QTY	Booked QTY	Actual QTY	% Finished	% Packed
934778	S2009186626	1200	1200	1200	100	100
934780	S2009186626	2400	2400	2400	100	100
	Total:	3600	3600	3600	100	100

2. AQL (Workmanship appearance & Function inspection findings) 🖾 Conformed 🗖 Not Conformed 🗍 Pending Combine sample size: 200pcs

Defect description		Critical	Major	Minor
For 934778: s/s: 67pcs				
Colour stain on product		0	0	1
Scratch on product		0	0	1
Poor printing on product		0	0	1
For 934780: s/s: 133pcs				
Poor plating on product		0	0	2
Dent mark on product		0	0	1
	Total defectives:	0	0	6
	Maximum allowed:	0	7	14

3. Field Test / On Site Test Results:

 \boxtimes Conformed \square Not Conformed \square Pending

Article	Test item	Sample size	Result	Remark / Findings
934778 934780	Assembly check	10pcs	Acceptable	
934778 934780	Function check under 4bar water pressure	All sample size	Acceptable	
934778 934780	Leakage test under 16bar water pressure	All sample size Acceptable		
934778 934780	Barcode scan	6pcs	Readable	
934778 934780	Batch code check	10pcs	Acceptable	20110725/30009
934778 934780	Go and no go gauge check	All sample size	Acceptable	
934778	3M test	10pcs	Acceptable	



4. Packaging & Product Conformity

Conformed Dot Conformed Pending

Article	QTY/ CTN X- Ply	QTY/ Inner X- Ply	Shipping Mark	Products	Bar Code On Unit	Bar Code On inner / outer carton	Bar code Readable
934778	2-Ply	2-Ply	Pass	Pass	3276005595347	03276005595361 03276005595354	Readable
934780	2-Ply	2-Ply	Pass	Pass	3276005595262	03276005595286 03276005595279	Readable

Remark: compare with client' ref sample, artwork, shipping mark, PO.



5. Product Size & Weight Check

Conformed D Not Conformed Pending

L,W, H: For Le	ngth,1	Width,	Heigh	t, Unit: ı	nm		Wt:	For	Weigh	t, Unit						
	Ref. Sample			Sample 1				Sample 2				Sample3				
Article 📢	L	w	н	Wt (bod y)	L	w	н	Wt	L	w	н	Wt	L	w	н	Wt
934778	/	/	/	368	Conform to ref sample			368	Conform to ref sample		369	Conform to ref sample		367		
934780	/	/	/	172		Conform to ref sample		173	Conform to ref sample			174	Conform to ref sample		173	

Note: client tolerance +/-2mm for size, +/-5% for weight

This document is issued by Troika Inspection Service Company.



Carton Size & Weight Check

Antiala	ength, Width, Height, Unit: C Data In PO			Outer Carton 1			r Weight, Unit: KG Outer Carton 2				Pallet					
Article	L	W	Н	Wt	L	W	Н	Wt	L	W	Н	Wt	L	W	Н	Wt
934778	60	41	28	23.5	60	42	28	23.5	60	42	28	23.6	/	/	/	/
934780	38	30	20	20	37	31	20	20.5	37	31	20	20.5	/	/	/	/

Remark: compare with client' PO data.

6. Attachment





934778-scratch on product.JPG





934780- item number not conform to ref (3).JPG

This document is issued by Troika Inspection Service Company.





934780- item number not conform to ref (2).JPG



934780- barcode not conform to ref (4).JPG



934780-def-poor plating on product (1).JPG


This document is issued by Troika Inspection Service Company.



934780- barcode not conform to ref (5).JPG



934780-dent mark on product.JPG



factory gate.JPG

V1.0 Page 5 of 15



Troika Inspection Service

Your Quality Solution Partner

Report No.: TIS-CTS-00000



storage.JPG



934778-export carton.jpg



934778-marking on color card (3).jpg

This document is issued by Troika Inspection Service Company.

934778-marking on color card (2).jpg

Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."

2010/05/05/010



Troika Inspection Service

Your Quality Solution Partner



934778-marking on color card (4).jpg



934778-marking on product (2).jpg



934778-product (1).jpg

Report No.: TIS-CTS-00000



934778-marking on product (1).jpg



934778-packing.jpg



934778-product (2).jpg

V1.0 Page 7 of 15



Troika Inspection Service

Your Quality Solution Partner

934778-product and ref.sample (1).jpg







934780-export carton.jpg

Report No.:TIS-CTS-00000



934778-product and ref.sample (2).jpg



934778-unit packing.jpg



934780-label on unit packing.jpg


V1.0 Page 8 of 15





934780-marking on color card (1).jpg






INTERNAL DE

Origem China

934780-marking on color card (3).jpg



934780-packing.jpg





934780-product (1).jpg

V1.0 Page 9 of 15



Your Quality Solution Partner

Report No.:TIS-CTS-00000



934780-product (2).jpg



934780-product and ref.sample (2).jpg



934778-3 M test.jpg

This document is issued by Troika Inspection Service Company.



934780-shipping mark, jpg



934780-unit packing.jpg



934778-assembly check.jpg

V1.0 Page 10 of 15

TIS Troika Inspection Service Your Quality Solution Partner

Report No.:TIS-CTS-00000



934778-barcode scan (1).jpg



934778-barcode scan (3).jpg



934778-function check (2).jpg



934778-barcode scan (2).jpg



934778-function check (1).jpg



934778-function check (3).jpg

This document is issued by Troika Inspection Service Company.

V1.0 Page 11 of 15





934778-gauge check (1).jpg







934778-gauge check (4).jpg



934778-leakage check.jpg

934778-gauge check (3).jpg



934778-gauge check (5).jpg

This document is issued by Troika Inspection Service Company.

V1.0 Page 12 of 15



934778-weight check (1).jpg

Report No.:TIS-CTS-00000



934778-weight check (2).jpg



934780-assembly check.jpg



934780-barcode scan (2).jpg

0 32 74005 33527 9 A1- 12" andar - Sala 2 4543-900

934780-barcode scan (1).jpg



934780-barcode scan (3).jpg

V1.0 Page 13 of 15





934780-function check.jpg



934780-gauge check (1).jpg



934780-gauge check (2).jpg



934780-gauge check (4).jpg



934780-gauge check (3).jpg



934780-gauge check (5).jpg

V1.0 Page 14 of 15





934780-gauge check (6).jpg



934780-weight check (1).jpg





934780-leakage check.jpg



934780-weight check (2).jpg

This document is issued by Troika Inspection Service Company.

V1.0 Page 15 of 15

Any holder of this document is advised that information contained hereon is solely limited to visual examination of the safely and readily accessible portions of the consignment and reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law."

-end-